

5649 SAPLINAS ROAD



**BUILDING AND STANDARDS BOARD AGENDA ITEM # 4 FOR
WEDNESDAY, OCTOBER 28, 2015**

**PLANNING & INSPECTIONS DEPARTMENT
BUILDING SAFETY DIVISION**

MEMORANDUM

October 19, 2015

TO: The Honorable Chairman and Board Members

THROUGH: Victor Morrison-Vega, Deputy Director, Planning & Inspections Department

FROM: Ron Roth, C.B.O., Deputy Building Official

SUBJECT: 5649 Saplinas Rd., El Paso, Texas, 79932-1956

The following is a brief chronology of the investigation of the referenced location:

- 1) First investigated on August 11th 2015. Recently investigated on August 20th, September 21st and October 19th 2015. This single family dwelling was built on or about 1988, constructed of conventional wood framing with stucco finish on the exterior and gypsum drywall on the interior and built up asphalt roof structure. The property was found open and extensively damaged by fire occurrences on or about April 26, 2015 and again August 15, 2015. Signs of illegal plumbing work were found in the structure. The exterior is littered with overgrown weeds, trash and debris property. Neighbors are concerned for vermin and health risks due to a refrigerator left with decaying food on the abandoned property which could pose a threat to their safety and wellbeing.
- 2) A certified condemnation letter was mailed to Joseph M. Entringer, 5649 Saplinas Rd. El Paso, TX 79932-1956, and 401 Verde Mar Pl. El Paso, TX 79912.
- 3) Certified notices of the public hearing scheduled for October 28, 2015, were mailed to the owners and all interested parties on October 06, 2015.
- 4) As of October 19, 2015, \$3,431.48 is owed in current taxes.

The owners have been notified of the property violations at this property. To date there has been no response or corrective action taken, and therefore the Department recommends that it be found:

- 1) That the structures be condemned as substandard, and unfit for habitation or use and a hazard to the public health, safety, and welfare; and
- 2) That the structures are not in substantial compliance with the municipal ordinances regulating fire protection, structural integrity, and disposal of refuse; and
- 3) That the structure's certificate of occupancy be revoked; and
- 4) That the structures cannot be rehabilitated; and
- 5) That the structures be demolished within thirty (30) days; and
- 6) That the premises be cleaned of all weeds, trash, and debris within 30 days and maintained clean thereafter; and
- 7) That upon failure by the owners or any other interested party to comply with the order of the Building and Standards Commission the City may take whatever action is necessary to bring the property into compliance, and place a lien on the property for the work which will be done by the City to include demolition.

Building Safety Division
August 11, 2015
NOTICE OF VIOLATION

ENTRINGER JOSEPH M.
5649 SAPLINAS RD.
EL PASO TX 79932-1956

Re: 5649 SAPLINAS RD.
Blk: 10 WEST GREEN
Lot: 15
Zoned: P – R 2 SC
Case Number: ENHS15-04307
91 7199 9991 7034 9452 7533

To All Owners, Lienholders, and Mortgagees:

An inspection at the above referenced address has revealed that the structure is in violation of the El Paso Municipal Code, Chapter 18.50, Property Maintenance Code, which states:

18.50.108.1 General.

When a structure or equipment is found by the Director to be unsafe, or when a structure is found unfit for human occupancy, or is found unlawful, such structure or equipment shall be condemned pursuant to the provisions of Title 2.38 of the Municipal Code.

The El Paso Municipal Code Chapter 18.50 International Property Maintenance Code defines unsafe structure as follows:

18.50.108.1.1 Unsafe Structures.

An unsafe structure is one that is found to be dangerous to the life, health, property or safety of the public or the occupants of the structure by not providing minimum safeguards to protect or warn occupants in the event of fire, or because such structure contains unsafe equipment or is so damaged, decayed, dilapidated, structurally unsafe or of such faulty construction or unstable foundation, that partial or complete collapse is possible.

18.50.108.1.2 Unsafe Equipment.

Unsafe equipment includes any boiler, heating equipment, elevator, moving stairway, electrical wiring or device, flammable liquid containers, or other equipment on the premises or within the structure that is in such disrepair or condition that such equipment is a hazard to life, health, property or safety of the public or occupants of the premises or structure.

18.50.108.1.3 Structure Unfit for Human Occupancy.

A structure is unfit for human occupancy whenever the Director finds that such structure is unsafe, unlawful or, because of the degree to which the structure is in disrepair or lacks maintenance, is unsanitary, vermin or rat infested, contains filth or contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public.

The structure located at **5649 Saplinas Rd.**, is in violation of the requirements found in the following sections of the 2009 International Property Maintenance Code as adopted in the El Paso City Code, Chapter 18.50, Property Maintenance Code:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition, All accessory structures, including detached garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]

- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]
- c. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 305.1, 305.2, 305.3, 305.4, 305.5, 305.6]
- d. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- e. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- f. All structures shall be kept free from insect and rodent infestation. All structures in which insects or rodents are found shall be promptly exterminated by approved processes that will not be injurious to human health. After pest elimination, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]
- g. The building must comply with the minimum criteria and conditions for light. [Sec.402.1, 402.2, 402.3]
- h. The building must comply with the minimum criteria and conditions for ventilation. [Sec.403.1, 403.2, 403.3, 403.4, 403.5]
- i. The requirement for Privacy, minimum room dimensions, prohibited occupancy or food preparation spaces not met. [Sec.404.1, 404.2, 404.3, 404.4, 404.5, 404.6, 404.7]
- j. The building must comply with the minimum criteria of the provisions for required facilities. [Sec. 502.1, 502.2, 502.3, 502.4,502.4.1, 502.5]
- k. The building must comply with the minimum criteria of the provisions for toilet rooms. [Sec. 503.1, 503.2, 503.3, 503.4]
- l. The building must comply with the minimum criteria of the provisions for plumbing systems and fixtures. [Sec. 504.1, 504.2, 504.3]
- m. The building must comply with the minimum criteria of the provisions for water systems. [Sec. 505.1, 505.2, 505.3, 505.4]
- n. The building must comply with the minimum criteria of the provisions for sanitary drainage systems. [Sec.506.1, 506.2, 506.3]
- o. The drainage of roofs and paved areas, yards and courts, and other open areas on the premises shall not be discharged in a manner that creates a public nuisance. [Sec. 507.1]
- p. The building must comply with the minimum criteria of the provisions for heating facilities. [Sec. 602.2, 602.3, 602.4, 602.5]
- q. All mechanical equipment and fireplaces shall be properly installed and maintained. [Sec.603.1, 603.2, 603.3, 603.4, 603.5, 603.6]
- r. All electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner. [Sec. 605.1, 605.2, 605.3]
- s. Duct systems shall be maintained free of obstructions and shall be capable of performing the required function. [Sec. 607.1]
- t. Means of egress & Emergency escape opening - A safe, continuous and unobstructed path of travel has not been provided from all points in the building or structure to the public way. [Sec. 702.1, 702.2, 702.3, 702.4]

- u. The required fire-resistance rating of fire-resistance-rated walls, fire stops, shaft enclosures, partitions and floors shall be maintained. [Sec. 703.1, 703.2]
- v. All systems, devices and equipment to detect a fire, actuate an alarm, or suppress or control a fire or any combination thereof shall be maintained in an operable condition at all times. [Sec. 704.1, 704.1.1, 704.2, 704.3, 704.4]
- w. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]
- x. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within **30** days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the Planning & Inspections Department, Building Safety Division.

As a result of the aforementioned violations, the following action may be taken:

- a. This case is being submitted to the City Building and Standards Commission for unsafe structures proceedings. The Building and Standards Commission will decide if the structure is unsafe and if it should be vacated and secured, or demolished as per Title 2.38 of the El Paso Municipal Code.
- b. By authority of Chapter 18.02.103.10.3.3 of the El Paso Municipal Code the electrical service at this property may be disconnected at the request of the City Development Department, Building Safety Division because of Electrical Code violations.

Many of these corrections will require a permit. Permits for commercial or rental property must be taken out by a bonded and insured contractor who is registered with the City of El Paso.

According to the real property records of El Paso County, you own the real property described in this notice. If you no longer own the property, you must execute an affidavit stating that you no longer own the property and stating the name and last known address of the person who acquired the property from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Building Safety Division office, 801 Texas Ave., El Paso, Texas, 79901, no later than the 20th day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice, even if you do not.

Should you have any questions regarding this matter, please contact me at (915) 212-1815 or (915) 240-2273.

Alexandro Esparza
Building Inspector

NOTICE OF PUBLIC HEARING

To all interested parties:

The owners, mortgagee, lien holders and any others with a legal interest in the property described below are hereby ordered to appear before the Building and Standards Commission, herein after referred to as the “Commission”, at the following time and place:

LOCATION: El Paso City Hall, City Council Chambers, 300 N. Campbell El Paso, Texas 79901

DATE: October 28, 2015

TIME: 5:30 p.m.

PROPERTY: 5649 Saplinas Rd. El Paso, Texas, 79932 also described as Lot 15, Block 10, WEST GREEN, an addition to the City of El Paso, El Paso County, Texas, according to the Plat Thereof recorded in Volume 63, Page 31, Plat Records of El Paso, County, Texas

The Property has been determined to be substandard based upon violations of the minimum standards of the 2009 Building Codes, adopted and incorporated in the El Paso City Code, Chapter 18, more specifically addressed below.

According to the real property records of El Paso County, and other relevant public records, Joseph M. Entringer A/K/A Joseph Entringer, 5649 Saplinas Rd., El Paso, Texas, 79932, is the owner, herein after referred to as the “Owner” of the Property. If you no longer own or have an interest in the Property, you must execute an affidavit stating that you no longer own or have an interest in the Property and stating the name and last known address of the person who acquired the property from you, if applicable. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Building and Safety Division, Planning & Inspections Department, 801 Texas, Avenue, El Paso, Texas, 79901, no later than the 20th day after the date you receive this notice. If you do not execute and deliver the affidavit, it will be presumed that you own or have an interest in the Property, even if you do not.

On or about August 11, 2015, an inspection of the Property was conducted by the Building and Safety Division and the following violations were identified:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition, All accessory structures, including detached garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9]
- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]

- c. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 305.1, 305.2, 305.3, 305.4, 305.5, 305.6]
- d. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6]
- e. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- f. All structures shall be kept free from insect and rodent infestation. All structures in which insects or rodents are found shall be promptly exterminated by approved processes that will not be injurious to human health. After pest elimination, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]
- g. The building must comply with the minimum criteria and conditions for light. [Sec.402.1, 402.2, 402.3]
- h. The building must comply with the minimum criteria and conditions for ventilation. [Sec.403.1, 403.2, 403.3, 403.4, 403.5]
- i. The requirement for Privacy, minimum room dimensions, prohibited occupancy or food preparation spaces not met. [Sec.404.1, 404.2, 404.3, 404.4, 404.5, 404.6, 404.7]
- j. The building must comply with the minimum criteria of the provisions for required facilities. [Sec. 502.1, 502.2, 502.3, 502.4,502.4.1, 502.5]
- k. The building must comply with the minimum criteria of the provisions for toilet rooms. [Sec. 503.1, 503.2, 503.3, 503.4]
- l. The building must comply with the minimum criteria of the provisions for plumbing systems and fixtures. [Sec. 504.1, 504.2, 504.3]
- m. The building must comply with the minimum criteria of the provisions for water systems. [Sec. 505.1, 505.2, 505.3, 505.4]
- n. The building must comply with the minimum criteria of the provisions for sanitary drainage systems. [Sec.506.1, 506.2, 506.3]
- o. The drainage of roofs and paved areas, yards and courts, and other open areas on the premises shall not be discharged in a manner that creates a public nuisance. [Sec. 507.1]
- p. The building must comply with the minimum criteria of the provisions for heating facilities. [Sec. 602.2, 602.3, 602.4, 602.5]
- q. All mechanical equipment and fireplaces shall be properly installed and maintained. [Sec.603.1, 603.2, 603.3, 603.4, 603.5, 603.6]
- r. All electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner. [Sec. 605.1, 605.2, 605.3]

- s. Duct systems shall be maintained free of obstructions and shall be capable of performing the required function. [Sec. 607.1]
- t. Means of egress & Emergency escape opening - A safe, continuous and unobstructed path of travel has not been provided from all points in the building or structure to the public way. [Sec. 702.1, 702.2, 702.3, 702.4]
- u. The required fire-resistance rating of fire-resistance-rated walls, fire stops, shaft enclosures, partitions and floors shall be maintained. [Sec. 703.1, 703.2]
- v. All systems, devices and equipment to detect a fire, actuate an alarm, or suppress or control a fire or any combination thereof shall be maintained in an operable condition at all times. [Sec. 704.1, 704.1.1, 704.2, 704.3, 704.4]
- w. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]

The Owner is entitled to show cause that the Property is safe, does not constitute a dangerous structure and should not be declared a nuisance and ordered abated by presenting relevant evidence and testimony. If the Owner advocates for repair, then they bear the burden of proof to demonstrate the scope of any work that may be required to bring the property into compliance with Chapter 18.50 and the time it will take to reasonably perform the work. The allowable time periods for repair are governed by Texas Local Government Code, Sections 214.001(h), (i), (j) and (k). Any document relied upon to demonstrate that the Property is safe or that it can be repaired must be presented to the Commission at the hearing, including building plans, specifications, drawings, or reports from professionals and any other relevant documentation.

If the Owner fails to comply with the order of the Commission the City may pursue one or more of the following actions:

Perform any and all work necessary to bring the property into compliance with the Commission's order;

Assess civil penalties, provided for in the Commission's order, in an amount not to exceed \$1,000 per day or \$10 per day if the Property has a homestead exemption, that will accrue interest of 10% per year until paid in full;

Appoint a receiver as permitted by state law; and

Any other remedies permitted by state law.

Commission orders may be appealed to the State District Court within 30 days of the Final order.

The Commission's authority and procedures in regard to a Dangerous Structure Hearing may be found in Chapter 2.38 of the El Paso City Code and in their duly adopted bylaws. The bylaws may be obtained at the Building and Safety Division, Planning & Inspections Department, 801 Texas Avenue, El Paso, Texas, 79901 or by calling (915) 212-1815.

This notice will be recorded in the real property records of El Paso County and will be binding on subsequent grantees, lien holders or other transferees of an interest in the Property.

The City Clerk is ordered to provide notice of this hearing to the record owners and all other interested parties, required by law, who are listed following this notice, and file this notice in the real property records of El Paso County.

FAILURE OF THE OWNER AND/OR LIENHOLDER OR MORTGAGEE TO TAKE THE ORDERED ACTION MAY RESULT IN THE CITY TAKING THE ORDERED ACTION AND FILING A LIEN AGAINST THE PROPERTY.

The City of El Paso appreciates your cooperation and prompt attention to remedying the nuisances on the Property. Please do not hesitate to contact me should you have any additional questions, comments or concerns relative to this notice.

APPROVED AS TO FORM

APPROVED AS TO CONTENT

Wendi N. Vineyard
Assistant City Attorney

Ron Roth, C.B.O.
Deputy Building Official

I, RICHARDA DUFFY MOMSEN, City Clerk of the City of El Paso, hereby certify that a true and correct copy of the foregoing Notice regarding the property located at 5649 Saplinas Rd., El Paso, Texas, 79932 was PUBLISHED in the official City newspaper on the ____ day of _____, 2015.

Richarda Duffy Momsen

I certify that a true and correct copy of the foregoing Notice regarding the property at 5649 Saplinas Rd., El Paso, Texas, 79932 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Joseph M. Entringer
A/K/A Joseph Entringer
5649 Saplinas Rd.
El Paso, Texas 79932-1956

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 5649 Saplinas Rd., El Paso, Texas, 79932 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Joseph M. Entringer
A/K/A Joseph Entringer
401 Verde Mar Pl.
El Paso, Texas 79912

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 5649 Saplinas Rd., El Paso, Texas, 79932 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Amber Entringer
10723 White Sands Dr.
El Paso, Texas 79924-1114

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 5649 Saplinas Rd., El Paso, Texas, 79932 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

State National Bank
P. O. Box 6050
El Paso, Texas 7999-5050

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 5649 Saplinas Rd., El Paso, Texas, 79932 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

F James Volk
601 North Mesa
El Paso, Texas 79901

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 5649 Saplinas Rd., El Paso, Texas, 79932 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Bank of Oklahoma, N.A.
7060 S. Yale Ste 200
Tulsa, OK 74136

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 5649 Saplinas Rd., El Paso, Texas, 79932 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Nicole Entringer
HC62 Box 5131
Thoreau, New Mexico 87323

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 5649 Saplinas Rd., El Paso, Texas, 79932 was HAND-DELIVERED to:

City of El Paso
C/O City Clerk
300 N. Campbell
El Paso, TX 79901

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 5649 Saplinas Rd., El Paso, Texas, 79932 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Governor of the Ysleta Del Sur Pueblo Indian Tribe
AKA Tigua Indian Community
119 S. Old Pueblo Road
El Paso, Texas 79907

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 5649 Saplinas Rd., El Paso, Texas, 79932 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso Central Appraisal District
5801 Trowbridge Ave.
El Paso, Texas 79925

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 5649 Saplinas Rd., El Paso, Texas, 79932 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso County Clerk, Probate Dept.
500 E. San Antonio Avenue, Suite 105
El Paso, Texas 79901

Date: _____
Time: _____
Inspector: _____

I certify that a true and correct copy of the foregoing Notice regarding the property at 5649 Saplinas Rd., El Paso, Texas, 79932 was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Delgado, Acosta, Spencer
Linebarger, Heard & Perez, LLP
Attn: Bonnie Cooper
221 N. Kansas, Suite 1400
El Paso, TX 79901

Date: _____

Time: _____

Inspector: _____

I certify that a true and correct copy of the foregoing Notice was POSTED at 5649 Saplinas Rd., El Paso, Texas, 79932.

Date: _____

Time: _____

Inspector: _____



UNSAFE STRUCTURES REPORT

PLANNING & INSPECTIONS BUILDING SAFETY

DATE OF EXAMINATION: September 21, 2015

REP. DISTRICT: 1

ADDRESS: 5649 Saplinas Rd.

ZONED: P – R 2 SC

LEGAL DESCRIPTION: 10 West Green Lot 15

OWNER: Entringer Joseph M.

ADDRESS: 5649 Saplinas Rd.
El Paso, TX 79932-1956

BUILDING USE: Abandoned Single-Family Dwelling

TYPE OF CONSTRUCTION: V, wood framing w/ stucco finish

FOOTINGS: Monolithic Concrete Slab

CONDITION: Unable to determine condition of footing due to subterranean placement. A structural engineer should be hired to evaluate actual condition.

FOUNDATION WALL: N/A

CONDITION: N/A

FLOOR STRUCTURE: Concrete and with some carpet and vinyl covering

CONDITION: Fair - Fire Damaged. Slab has been broken in places to perform plumbing work; a structural engineer should be hired to evaluate actual condition.

EXTERIOR WALLS: Wood framing with stucco finish.

HEIGHT: 10' - 15' +/-

THICKNESS: 4' – 6' +/-

CONDITION: Poor – Fire Damaged. A structural engineer should be hired to evaluate the structural elements of the building and submit a report on the corrections required to make the building safe.

INTERIOR WALLS & CEILINGS: Wood framing w/ gypsum board covering

CONDITION: Poor – Fire Damaged. A structural engineer should be hired to evaluate the structural elements of the building and submit a report on the corrections required to make the building safe.

ROOF STRUCTURE: Wood frame built up roof covering.

CONDITION: Poor – Fire Damaged. A registered roofing contractor licensed in the state of Texas must be hired to evaluate the roofing system and submit a report of required corrections to bring the roof system into code compliance.

DOORS, WINDOWS, ETC.: Wood frame doors and aluminum frame windows.

CONDITION: Poor – Fire Damaged. Several windows and doors are missing or broken and will need to be repaired so they are operational and meet egress requirements.

MEANS OF EGRESS: Does not meet code requirements.

CONDITION: Poor – Fire Damaged. Windows and doors must be repaired or replaced.

PLUMBING: A licensed plumber should be hired to evaluate and bring the system up to code.

CONDITION: Poor – Fire Damaged. Signs of illegal plumbing work done, and the rest of fixtures are severely damaged by fire occurrence.

ELECTRICAL: A licensed electrician should be hired to evaluate and bring the system up to code.

CONDITION: Poor – Fire Damaged. Fixtures and wire are severely damaged by fire occurrence.

MECHANICAL: A licensed mechanical contractor should be hired to evaluate bring the system up to code.

CONDITION: Poor – Fire Damaged. Ducts, vents and units are severely damaged by fire occurrence.

IF CONDEMNED, HOW MANY PERSONS WILL BE AFFECTED: 0

WARNING POSTED: Yes

BARRICADED: No

POLICE AID REQD.: No

REMARKS: First investigated on August 11th 2015. Recently investigated on August 20th, September 21st and October 19th 2015. This single family dwelling was built on or about 1988, constructed of conventional wood framing with stucco finish on the exterior and gypsum drywall on the interior and built up asphalt roof structure. The property was found open and extensively damaged by fire occurrences on or about April 26, 2015 and again August 15, 2015. Signs of illegal plumbing work were found in the structure. The exterior is littered with overgrown weeds, trash and debris throughout the property. Neighbors are concerned for vermin and health risks due to a refrigerator left with decaying food on the abandoned property which could pose a threat to their safety and wellbeing.

Alexandro Esparza

Building Inspector

TAX REPORT

Appraisal & Collection Technologies - EL PASO

Action Edit Query Record Field Help Entitlements Accounts Statements Window

Account Status

Prev. Acc... Next Acc... Prev. Owner Next Owner Acct History Acct Summary **Notes** Documents Go To:

EVAR
ACT8006 v1.268 10/19/2015 10:32:35
ACTEP

STATUS DETAIL Expand Fees Summary

Account Information

Account No. W144-999-0100-1500 Roll Code REAL PROPERTY

Certified Owner ENTRINGER JOSEPH M

Parcel Address 5649 SAPLINAS RD

Amount Due as of 10/19/2015 CAD No. 350617

Tax Units

Tax Unit Description

List of Tax Units

1 3 6 7 8

AG INCLUDED Remove Fees Countywide

Tax Unit, Yr, Rec. Type

Tax Unit Year Rec. Type Multi Select

Amount Due/Paid Information

Year	Gross Value	H	O	V	D	Excodes	Base Levy	Paid Levy	Write-Off	Remaining Levy	Fees	Refund	Amount Due
2015	\$137,066	Y				Excodes	\$3,431.48	\$0.00	\$0.00	\$3,431.48	\$0.00	\$0.00	\$3,431.48
2014	\$136,330	Y				Excodes	\$3,487.51	\$3,487.51	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2013	\$136,330	Y				Excodes	\$3,419.98	\$3,419.98	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2012	\$136,330	Y				Excodes	\$3,317.86	\$3,317.86	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2011	\$136,330	Y				Excodes	\$3,257.10	\$3,257.10	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2010	\$136,330	Y				Excodes	\$3,228.80	\$3,228.80	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2009	\$137,538	Y				Excodes	\$3,192.72	\$3,192.72	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2008	\$139,066	Y				Excodes	\$3,194.00	\$3,194.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2007	\$143,470	Y				Excodes	\$2,909.64	\$2,909.64	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Totals							\$52,311.98	\$48,880.50	\$0.00	\$3,431.48	\$199.14	\$0.00	\$3,431.48

Last Payment Date

Last Payer

Alert